




44661013 44662023



WICHTIG - FÜR SPÄTERE VERWENDUNG
AUFBEWAHREN - SORGFÄLTIG LESEN

AVIS - Ces instructions doivent être sauvegardées
Pour utilisation future - Les instructions doivent
être suivies

IMPORTANTE, conservar estas instrucciones
para futuro uso. Siga estas instrucciones atentamente

VIGTIGT - Samlevejledningen skal opbevares
i arkiv til senere brug - Skal gennemlæses nøje

NOTICE - These instructions must be saved
for future use - Instructions must be followed


44661013

TEILCHECKLISTE
LISTE DE CONTROLE
LISTADO DE CONTROL
TJEKLISTE
CHECK LIST

Réf./No.	Réf./Art.	Qty./Stck./Quantité	Size / Maß / Dimension (mm)	Packed in box	✓
1	32839800	1	1101x600x18	1	
2	32839900	2	165x579x15	1	
3	32850400	1	1101x600x15	1	
4	32850900	1	165x560x15	1	
5	32851400	2	527x165x15	1	
6	228523	4	222x50x50	1	
7	32852411	2	557x159x18	1	
8	32852500	2	335x130x12	1	
9	32852600	2	335x130x12	1	
10	32852700	2	478x128x12	1	
11	32852800	2	488x331x3	1	

44662023










Réf./No.	Réf./Art.	Qty./Stck./Quantité	Size / Maß / Dimension (mm)	Packed in box	✓
1	32839822	1	1101x600x18	1	
2	32839922	2	165x579x15	1	
3	32850422	1	1101x600x15	1	
4	32850922	1	165x560x15	1	
5	32851422	2	527x165x15	1	
6	228523	4	222x50x50	1	
7	32852422	2	557x159x18	1	
8	32852522	2	335x130x12	1	
9	32852622	2	335x130x12	1	
10	32852722	2	478x128x12	1	
11	32852822	2	488x331x3	1	



TEILCHECKLISTE - LISTE DE CONTROLE - LISTADO DE CONTROL- TJEKLISTE - CHECK LIST

Réf./No.	Réf./Art.	Qty./Stck./Quantité	✓
A	228530	20	
B	228530	13	
C	228530	13	
J	228530	1	
M	228232	2	
N	228232	2	
Q	228530	21	
R	228530	13	
V	228530	1	
X	228530	8	

Réf./No.	Réf./Art.	Qty./Stck./Quantité	✓
Y	228530	8	
Z	228530	4	
AC	228530	8	
AG	228530	24	
AM	228530	16	
AN	228529	2	
AO	228529	2	
AP	228529	2	
AQ	228529	2	

20 - A  Ø 8x30mm	13 - B  Ø 6x34mm	13 - C  Ø 15x12mm	1 - J  4mm	2 - M  20mm	2 - N  M4x20mm
21 - Q  Ø 20mm	13 - R  Ø 5x38mm	1 - V  3mm	8 - X  Ø 4x20mm	8 - Y  Ø 12x9mm	4 - Z  Ø 6x30mm
8 - AC  Ø 4x30mm	24 - AG  Ø 3.5x14mm	16 - AM  M6x16mm	2 - AN  300mm	2 - AO  300mm	2 - AP  300mm
2 - AQ  300mm					


Geehrter Kunde.
Hier haben Sie die Möglichkeit die mitgelieferten
Schrauben nachzumessen.





Cher Client.
La règle ci jointe vous permet de mesurer la visserie.




Estimado cliente.
aquí podrá medir la tornillería adjunta.



Kære kunde.
Her har De muligheden for at måle medsendte beslag.



Dear Customer.
Below you have the opportunity to measure the
Enclosed Hardware.














6

R x 13



V x 1




7

AM x 16




J x 1







8

Q x 9





II








x2









x2






x2



12



13

